



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	76	<b>Date:</b>	8/27/2004	<b>MeterBasin:</b>	01_WR21
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5723		Clover	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	8=Yard-Back	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 1

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0827-2004\T-1\PLAYER\_A\A\_2004\_0827Image0001.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

76

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\76.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	76	<b>Date:</b>	8/27/2004	<b>MeterBasin:</b>	01_WR21
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5713		Park Heights	AVE

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	100	

**Comments:** at side of church building by Clover & Manhattan

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 1

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0827-2004\T-1\PLAYER\_B\B\_2004\_0827Image0001.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

76

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\76.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	76	<b>Date:</b>	8/27/2004	<b>MeterBasin:</b>	01_WR21
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5723		Clover	ROAD

<b>Source Type:</b>	01= Main Sewer	<b>Location:</b>	8=Yard-Back	<b>Severity:</b>
---------------------	----------------	------------------	-------------	------------------

<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	200
----------------	----------	-----------------------	-----

**Comments:** ground around manhole

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 2

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0827-2004\T-1\PLAYER\_B\B\_2004\_0827Image0002.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

76

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\76.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	77	<b>Date:</b>	8/27/2004	<b>MeterBasin:</b>	01_WR19
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5800		Clover	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	8=Yard-Back	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25	

**Comments:** alley between Clover and Glen

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 2

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0827-2004\T-1\PLAYER\_A\A\_2004\_0827Image0002.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.






# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

77

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\77.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	77	<b>Date:</b>	8/27/2004	<b>MeterBasin:</b>	
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	5815	<b>Street Prefix:</b>		<b>Street Name:</b>	Park Heights	<b>Street Type:</b>	AVE
<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	8=Yard-Back	<b>Severity:</b>			
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0				
<b>Comments:</b>							

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 3

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0827-2004\T-1\PLAYER\_B\B\_2004\_0827Image0003.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

77

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\77.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.




# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	77	<b>Date:</b>	8/27/2004	<b>MeterBasin:</b>	
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>	
5815		Park Heights	AVE	
<b>Source Type:</b>	01= Main Sewer	<b>Location:</b>	8=Yard-Back	<b>Severity:</b>
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	0	
<b>Comments:</b>	alley			

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 4

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0827-2004\T-1\PLAYER\_B\B\_2004\_0827Image0004.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

77

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\77.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	78	<b>Date:</b>	8/27/2004	<b>MeterBasin:</b>	01_WR19
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5750		Park Heights	AVE
<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25
<b>Comments:</b>			

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 3

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0827-2004\T-1\PLAYER\_A\A\_2004\_0827Image0003.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 78

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\78.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.




# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	78	<b>Date:</b>	8/27/2004	<b>MeterBasin:</b>	
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	5800	<b>Street Prefix:</b>		<b>Street Name:</b>	Park Heights	<b>Street Type:</b>	AVE
<b>Source Type:</b>	02= Service Line	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>			
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	150				
<b>Comments:</b>	ground						

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 5

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0827-2004\T-1\PLAYER\_B\B\_2004\_0827Image0005.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.






# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

78

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\78.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	78	<b>Date:</b>	8/27/2004	<b>MeterBasin:</b>	01_WR19
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>	
5806		Park Heights	AVE	
<b>Source Type:</b>	05= Downspout	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25	
<b>Comments:</b>				

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 6

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0827-2004\T-1\PLAYER\_B\B\_2004\_0827Image0006.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

78

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\78.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	78	<b>Date:</b>	8/27/2004	<b>MeterBasin:</b>	01_WR19
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>	
5806		Park Heights	AVE	
<b>Source Type:</b>	05= Downspout	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25	
<b>Comments:</b>	down spout			

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 6

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0827-2004\T-1\PLAYER\_B\B\_2004\_0827Image0006.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

78

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\78.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	78	<b>Date:</b>	8/27/2004	<b>MeterBasin:</b>	01_WR19
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	4	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>	
5806		Park Heights	AVE	
<b>Source Type:</b>	05= Downspout	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25	
<b>Comments:</b>				

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 7

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0827-2004\T-1\PLAYER\_B\B\_2004\_0827Image0007.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



**Sketch No:**

78

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\78.tif

**Image Status:** Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	78	<b>Date:</b>	8/27/2004	<b>MeterBasin:</b>	01_WR19
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	5	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5806		Park Heights	AVE

<b>Source Type:</b>	02= Service Line	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	75	

**Comments:** ground

## SMOKE TEST PHOTOS



**Photo No:** 10

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0827-2004\T-1\PLAYER\_B\B\_2004\_0827Image0010.JPG

**Image Status:** Image found and displayed.



**Photo No:** 19

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\Retakes\UTID78-B5\2005\_0523Image019.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



**Sketch No:**

78

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\78.tif

**Image Status:** Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	78	<b>Date:</b>	8/27/2004	<b>MeterBasin:</b>	01_WR19
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	6	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	5806	<b>Street Prefix:</b>		<b>Street Name:</b>	Park Heights	<b>Street Type:</b>	AVE
<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>			
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	100				
<b>Comments:</b>							

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 11

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0827-2004\T-1\PLAYER\_B\B\_2004\_0827Image0011.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 78

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\78.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	78	<b>Date:</b>	8/27/2004	<b>MeterBasin:</b>	01_WR19
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	Y
<b>Defect No:</b>	7	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>	
5814		Park Heights	AVE	
<b>Source Type:</b>	14= Catch Basin	<b>Location:</b>	2=Paved Asphalt	<b>Severity:</b>
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	13000	
<b>Comments:</b>	street drainage			

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 12

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0827-2004\T-1\PLAYER\_B\B\_2004\_0827Image0012.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 78

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\78.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	78	<b>Date:</b>	8/27/2004	<b>MeterBasin:</b>	01_WR19
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	8	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5806		Park Heights	AVE
<b>Source Type:</b>	05= Downspout	<b>Location:</b>	9=Yard-Side
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25
<b>Comments:</b>			

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 8

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0827-2004\T-1\PLAYER\_B\B\_2004\_0827Image0008.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.






# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 78

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\78.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	78	<b>Date:</b>	8/27/2004	<b>MeterBasin:</b>	01_WR19
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	9	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5806		Park Heights	AVE
<b>Source Type:</b>	05= Downspout	<b>Location:</b>	9=Yard-Side
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25
<b>Comments:</b>			

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 9

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0827-2004\T-1\PLAYER\_B\B\_2004\_0827Image0009.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 78

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\78.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

---

<b>Unique Test ID</b>	79	<b>Date:</b>	8/27/2004	<b>MeterBasin:</b>	
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	0	<b>Setup No:</b>	4	<b>Priority CCTV:</b>	

---

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
---------------------	-----------------------	---------------------	---------------------

<b>Source Type:</b>	<b>Location:</b>	<b>Severity:</b>
<b>Sector:</b>	<b>Drainage Area:</b> 0	
<b>Comments:</b> No defects observed		

---

## SMOKE TEST PHOTOS

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 79

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\79.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

---

<b>Unique Test ID</b>	79	<b>Date:</b>	8/27/2004	<b>MeterBasin:</b>	
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	0	<b>Setup No:</b>	4	<b>Priority CCTV:</b>	

---

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
---------------------	-----------------------	---------------------	---------------------

<b>Source Type:</b>	<b>Location:</b>	<b>Severity:</b>
<b>Sector:</b>	<b>Drainage Area:</b> 0	
<b>Comments:</b> No defects observed		

---

## SMOKE TEST PHOTOS

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

79

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\79.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	80	<b>Date:</b>	8/27/2004	<b>MeterBasin:</b>	01_WR21
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	5	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5503		Magnolia	AVE

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 4

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0827-2004\T-1\PLAYER\_A\A\_2004\_0827Image0004.JPG

**Image Status:** Image found and displayed.



**Photo No:** 5

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0827-2004\T-1\PLAYER\_A\A\_2004\_0827Image0005.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 80

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\80.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	80	<b>Date:</b>	8/27/2004	<b>MeterBasin:</b>	01_WR21
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	5	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5611		Magnolia	AVE

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 6

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0827-2004\T-1\PLAYER\_A\A\_2004\_0827Image0006.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 80

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\80.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.